

Bench maintenance - Photo Example

CLIENT	Demonstration Only
SITE	DuPont Circle, Washington, DC
DATE	Oct 2, 2026

Illustrative report assembled in ReportMason on October 2, 2026. The date above and imported photo times refer to this demonstration, not to the maintenance work. Before and after photos: NPS / Kelsey Graczyk. Source: NPS article, The Work Behind the Welcome, June 5, 2026. The original work was carried out by NPS, not a ReportMason customer. No NPS endorsement is implied. No claim to original U.S. Government works.

BEFORE



Imported: Oct 2, 2026, 2:06 PM

Before: worn seat boards and missing backrest sections are visible in the published photo. Photo: NPS / Kelsey Graczyk.

AFTER



Imported: Oct 2, 2026, 2:06 PM

After: continuous seat and backrest boards have a dark painted finish. This photo shows the visible result; it does not establish a safety inspection. Photo: NPS / Kelsey Graczyk.